

CITY OF POMONA

Storm Water Pollution Prevention For Scrap and Waste Recycling Facilities

Best Management Practices (BMPs)

Inbound Material Control

Establish for rejecting or inspecting materials. Create a program for inspecting, handling, storing and disposing of lead-acid batteries, hazardous wastes, and other non-hazardous residual fluids. Procedures should describe handling of cracked and broken batteries and disposal of leaking battery acid. Give guidelines for properly handling industrial turnings and cuttings to prevent cutting oils and metallic fines from coming in contact with runoff.

Encourage suppliers of scrap, waste and other salvageable materials to drain residual fluids and reduce the volume of semi-solid and liquid residues in aluminum and plastic containers prior to bringing the material to the facility.

Material Storage

Store all materials and waste indoors or in covered areas with curbing, berms, or other containment measures. Surfaces of secondary containment areas should be adequately sealed to prevent leaks. Store the equivalent of one day's average volume of lightweight recyclable materials indoors. Separate all scrap batteries and segregate hazardous and flammable wastes to comply with National Fire Protection Association (NFPA) guidelines.

Store materials in appropriate containers near the point of use or production of the materials (i.e. shredded materials and fluff). Make sure that all storage containers and drums are in good condition and meet NFPA guidelines. Clearly label all containers and include necessary warnings and special handling instructions.

In the storage areas, put individual containers on pallets. Limit the stack height of individual containers/drums and put straps or plastic wrap around the drums to provide stability. Provide adequate clearance to allow material movement and access by material handling equipment.

Inspections and Maintenance

Regularly inspect material storage, handling and transfer area, equipment, containment areas. Storage and waste containers/drums, and bulk liquid tanks for spills, leaks, signs of corrosion, worn parts or components, deterioration of flanges, and leaking seals and gaskets. Immediately repair any problems.

Conduct routine preventive maintenance of equipment, control measures such as oil/water separators, and storage and containment areas. Conduct periodic non-destructive testing (NDT) of all bulk storage tanks for signs of deteriorating structural integrity.

Facility Operations

Drain and collect liquids in a designated area. Put a cover over and secondary containment around all liquid waste transfer facilities.

Conduct processing operations indoors or place process equipment under cover and prevent runoff from coming in contact with the equipment. Stabilize high traffic areas around the equipment.

Prohibit illicit discharges and illegal dumping to floor drains that are connected to the storm drain system.

Spills and Facility Clean Up

Establish spill prevention and response procedures and use dry methods to clean up spills. Keep an adequate supply of dry clean up materials readily accessible.


Schedule frequent cleaning of accumulated fluids and particulate residue around all scrap processing equipment, storage containers, and high traffic areas. Regularly sweep all traffic and storage areas to minimize particulate and residual materials buildup. Prohibit washing down of material storage and tipping floor areas, unless approval is granted by the wastewater treatment plant to discharge wash waters to the sanitary sewer.

Numbers to Call for More Information

Department of Toxic Substances Control (916) 324-1826
REPORT ILLEGAL DUMPING (800) 936-1409

Scrap and Waste Recycling Facilities

BEST MANAGEMENT PRACTICES



Frequently inspect and clean processing equipment and storage areas.


Inspeccione y limpie con frecuencia el equipo de procesamiento y las áreas de almacenamiento.

How to Prevent Stormwater Pollution at a Scrap and Waste Recycling Facility



Immediately clean up spills using dry methods.

Limpie cualquier reguero inmediatamente con materiales secos.



Cover and contain storage areas and process equipment.

Cubra y contenga las áreas de almacenamiento y el equipo de proceso.

Enforce recyclable material acceptance policies.

Practique las políticas de aceptación de materiales reciclables.